IN THE DRAWING

A REPLACEMENT SHEET of Fig. 2 is attached to delete the hollow center of drive head 23 and its knob top in correspondence with Fig. 1.

REMARKS

As shown by the copy filed February 25, 2005, of a letter of June 4, 2004, to the International Preliminary Examining Authority, the above changes were made at the behest of the Australian Patent Office for the priority application after the International Preliminary Examination Report had issued.

Reconsideration and allowance are, therefore, requested.

Respectfully submitted,

William R. Evans c/o Ladas & Parry LLP 26 West 61st Street

New York, New York 10023

Reg. No. 25858

Tel. No. (212) 708-1930